
Stencil with frame
BGA
Stand
Table
Tighten screw to clamp BGA
Jig with BGA clamp
Tweezer holes for safe removal of BGA
Changing model by changing this table plate
Precision alignment thru these pins
Press this handle down to separate stencil from BGA vertically with precision
mini squeegee with holder
Auto level to lock position for removal of reballed BGA after separated from stencil
Stencil with frame for spheres or solderballs placements
Collector box for excess spheres or solderballs
Stencil with frame for flux or solderpaste applications
Changing stencil by loosening these screws
Precision alignment thru these location holes on frame & stencils
Escape for excess spheres or solderballs