



Plate 1 & 2 clamp laser cut stencil

Plate 1

Laser cut
stencil

Plate 1 for application of flux or solder paste.

Plate 2 for application of solder balls

BGA manual
screen printer

Plate 2

Plate 3

Plate 3 pushes BGA up, in contact with stencil

Plate 3